

Fig. 1





Fig. 2



*Fig. 3*




Fig. 4





Fig. 5



*Fig. 6*





Fig. 7

0077110 "296T3460



*Fig. 8*




Fig. 9






Fig. 10



*Fig. 11*



*Fig. 12*






Fig. 13



*Fig. 14*



*Fig. 15*

001110 " 89613460




Fig. 16




Fig. 17A




Fig. 17B




Fig. 17C




Fig. 17D

GUTTET 00-32672460




Fig. 18




Fig. 19

ID: 970818B 56483-2A CALCINED  
FILE: 970818B.MDI SCAN: 1-10/.05/10/#181. ANODE: CU




Fig. 20

ID: 970818C 56483-5A CALCINED  
FILE: 970818C.MDI SCAN: 1-10/05/10/#181. ANODE: CU




Fig. 21